

All Program List

P0

LBL1 SDMS HLT
Min01 HLT
Min02 HLT
Min03 HLT
Min04 - MR02) R>P (MR03 - MR01) = HLT
X<>Y X>=0 GOT01
+ 360 = GOT01

P1

DEG AC 111 HLT
AC GSBP7
LBL1 GSBP8
GSBP5
AC GOT01

P2

DEG AC 112 HLT
AC HLT
Min07 AC HLT
Min08 AC GSBP7
LBL1 AC HLT
Min09 AC HLT
Min02 GSBP6
Min04 HLT
Min02 GSBP6
Min10 HLT
Min03 GSBP9
ABS Min03 MR05 Min16 GSBP5
MR03 HLT
MR08 - MR09 + MR16 = HLT
+ MR07 = HLT
GOT01

P3

NOP NOP NOP NOP NOP NOP NOP DEG AC 113 HLT
AC GSBP7
LBL1 AC GSBP8
GSBP5
MR00 Min17 MR01 Min18 MRF - 180 = Min19 GOT01

P4

DEG AC 114 HLT
AC HLT
Min07 AC HLT

Min08
LBL1 AC HLT
Min09 AC HLT
Min02 GSBP6
Min10 HLT
Min03 GSBP9
MR06 HLT
MR05 + MR08 - MR09 = HLT
+ MR07 = HLT
GOTO1

P5

MR04 + MR19 - 360 =
LBL1 X>=0 GOTO2
+ 360 = GOTO1
LBL2 MinF SDMS HLT
Min10 GSBP9
HLT
MR05 HLT
MR17 + MR06 = Min00 HLT
MR18 + MR05 = Min01 HLT

P6

MR02 INT + (MR02 FRAC * 2 10^X) Min14 INT / 60 + MR14 FRAC / 36 = Min15

P7

HLT
Min17 AC HLT
Min18 AC HLT
Min02 GSBP6
Min19

P8

HLT
Min02 GSBP6
Min04 HLT
Min03

P9

MR03 P>R MR10 = Min05 X<>Y Min06
END

Memory List

M00= 0.
M01= 0.
M02= 0.
M03= 0.
M04= 0.

M05= 0.
M06= 0.
M07= 0.
M08= 0.
M09= 0.
M0F= 0.

M10= 0.
M11= 0.
M12= 0.
M13= 0.
M14= 0.
M15= 0.
M16= 0.
M17= 0.
M18= 0.
M19= 0.
M1F= 0.

M20= 0.
M21= 0.
M22= 0.
M23= 0.
M24= 0.
M25= 0.
M26= 0.
M27= 0.
M28= 0.
M29= 0.
M2F= 0.

M30= 0.
M31= 0.
M32= 0.
M33= 0.
M34= 0.
M35= 0.
M36= 0.
M37= 0.
M38= 0.
M39= 0.
M3F= 0.

M40= 0.
M41= 0.
M42= 0.
M43= 0.
M44= 0.
M45= 0.
M46= 0.
M47= 0.
M48= 0.
M49= 0.
M4F= 0.

M50= 0.

M51= 0.
M52= 0.
M53= 0.
M54= 0.
M55= 0.
M56= 0.
M57= 0.
M58= 0.
M59= 0.
M5F= 0.

M60= 0.
M61= 0.
M62= 0.
M63= 0.
M64= 0.
M65= 0.
M66= 0.
M67= 0.
M68= 0.
M69= 0.
M6F= 0.

M70= 0.
M71= 0.
M72= 0.
M73= 0.
M74= 0.
M75= 0.
M76= 0.
M77= 0.
M78= 0.
M79= 0.
M7F= 0.

M80= 0.
M81= 0.
M82= 0.
M83= 0.
M84= 0.
M85= 0.
M86= 0.
M87= 0.
M88= 0.
M89= 0.
M8F= 0.

M90= 0.
M91= 0.
M92= 0.
M93= 0.
M94= 0.
M95= 0.
M96= 0.
M97= 0.
M98= 0.

M99= 0.

M9F= 0.

→