

All Program List

P0

```

DEG "ISa" HLT
GSBP7
LBL1 "A0" HLT
Min02 GSBP6
Min04 "A1" HLT
Min02 GSBP6
Min08 +/- + 180 = X>=0 GOT02
+ 180 = Min08
LBL2 MR08 +/- + 180 - MR04 = Min09 MR16 * MR08 SIN / MR09 SIN = Min03 GSBP5
GOT01

```

P1

```

"T1" HLT
GSBP7
LBL1 "OA" HLT
Min02 GSBP6
Min04 "L" HLT
Min03 X>=0 GOT02
GSBP9
SIN * MR03 ABS = ABS Min03 FIX3 "L#####" HLT
LBL2 GSBP5
GOT01

```

P2

```

"T2" HLT
"GH" HLT
Min07 "IH" HLT
Min08 GSBP7
LBL1 "FH" HLT
Min09 "OA" HLT
Min02 GSBP6
Min04 GSBP9
"L" HLT
Min03 P>R MR10 = Min05 X<>Y ABS Min03 MR05 Min16 GSBP5
MR16 Min05 MR03 FIX3 GSBP8
GOT01

```

P3

```

"ISd" HLT
MAC GSBP7
"L" HLT
Min03 GSBP5
MR00 Min17 MR01 Min18 MR10 + 90 = Min19
LBL1 "L(-:)" HLT
Min03 GSBP5
GOT01

```

P4

```

"Cr" HLT

```

```

"GH" HLT
Min07 "IH" HLT
Min08
LBL1 "FH" HLT
Min09 GSBP9
"L" HLT
Min03 P>R MR10 = Min05 X<>Y Min06 FIX3 GSBP8
GOT01

```

P5

```

MR04 + MR19 - 360 =
LBL1 X>=0 GOT02
+ 360 = GOT01
LBL2 MinF SDMS HLT
Min10 MR03 P>R MR10 = Min05 X<>Y Min06 FIX3 "x#####" HLT
MR05 FIX3 "y#####" HLT
MR17 + MR06 = Min00 FIX3 "X#####" HLT
MR18 + MR05 = Min01 FIX3 "Y#####" HLT

```

P6

MR02 INT + (MR02 FRAC * 2 10^X) Min14 INT / 60 + MR14 FRAC / 36 = Min15

P7

```

DEG "Re X0" HLT
Min17 "Y0" HLT
Min18 "X1" HLT
Min13 "Y1" HLT
Min14 - MR18 ) R>P ( MR13 - MR17 ) = Min16 X<>Y Min19 X>=0 GOT02
+ 360 = Min19
LBL2 SDMS HLT
MR16 FIX3 "L#####" HLT

```

P8

```

"L#####" HLT
MR05 + MR08 - MR09 = FIX2 "h#####" HLT
+ MR07 = FIX2 "EL#####" HLT

```

P9

```

"V" HLT
Min02 GSBP6
X>=0 GOT01
+ 90 = X>=0 GOT01
+ 360 = Min10
LBL1
END

```

Memory List

```

M00= 6.382598628E 03
M01=-8.646991212E 03
M02= 3.182315E 02
M03= 4.768499226E 02

```

M04= 3. 042444444E 01
M05= 4. 742417882E 02
M06=-4. 980537163E 01
M07= 0.
M08= 4. 16125E 01
M09= 1. 079630556E 02
M0F= 3. 54004714E 02

M10= 3. 54004714E 02
M11= 0.
M12= 0.
M13= 6. 02688E 03
M14= 2. 315E 01
M15= 3. 183875E 02
M16= 6. 830498825E 02
M17= 6. 432404E 03
M18=-9. 121233E 03
M19= 3. 235802696E 02
M1F= 0.

M20= 0.
M21= 0.
M22= 0.
M23= 0.
M24= 0.
M25= 0.
M26= 0.
M27= 0.
M28= 0.
M29= 0.
M2F= 0.

M30= 0.
M31= 0.
M32= 0.
M33= 0.
M34= 0.
M35= 0.
M36= 0.
M37= 0.
M38= 0.
M39= 0.
M3F= 0.

M40= 0.
M41= 0.
M42= 0.
M43= 0.
M44= 0.
M45= 0.
M46= 0.
M47= 0.
M48= 0.
M49= 0.
M4F= 0.

M50= 0.
M51= 0.
M52= 0.
M53= 0.
M54= 0.

M55= 0.
M56= 0.
M57= 0.
M58= 0.
M59= 0.
M5F= 0.

M60= 0.
M61= 0.
M62= 0.
M63= 0.
M64= 0.
M65= 0.
M66= 0.
M67= 0.
M68= 0.
M69= 0.
M6F= 0.

M70= 0.
M71= 0.
M72= 0.
M73= 0.
M74= 0.
M75= 0.
M76= 0.
M77= 0.
M78= 0.
M79= 0.
M7F= 0.

M80= 0.
M81= 0.
M82= 0.
M83= 0.
M84= 0.
M85= 0.
M86= 0.
M87= 0.
M88= 0.
M89= 0.
M8F= 0.

M90= 0.
M91= 0.
M92= 0.
M93= 0.
M94= 0.
M95= 0.
M96= 0.
M97= 0.
M98= 0.
M99= 0.
M9F= 0.